



सत्यमेव जयते

भारत-सरकार
GOVERNMENT OF INDIA

केंद्रीयलोकनिर्माणविभाग

CENTRAL PUBLIC WORKS DEPARTMENT

o/o the Executive Engineer,

Bengaluru Central Division-2, CPWD, 12th floor, Near Domlur Flyover,
Sir Visveswraya Kendriya Bhawan Domlur, Bengaluru-560071

Tel: 080-25356733

E-mail: bcd2cpwd1@gmail.com




ख्या.24(4)/ बीसीडी-II/2022-23/ 79215

दिनांक. 8.04.2022

सेवामें,

The Principal,
Kendriya Vidyalaya,
No.1, ASF Jalahalli (W)
Bangalore – 560015.



विषय:-Submission of stability/ Conditional Assessment Report for the Kendriya Vidyalaya No.2, Air Force Station, Jalahalli (East), Bangalore- 560014.

महोदय,

Please find enclosed herewith stability/ Conditional Assessment Report prepared by experts from Bangalore University Department of Civil Engineering for further necessary action at your end.

The report has been scrutinised and observation are as under.

1. The building structure is stable and safe for running school.
2. The seepage and leakages observed are to be arrested immediately to maintain stability and stop deterioration of the structure.
3. Places where concrete cover are spalling off need to be treated immediately as it may cause minor hazards for school children and also to maintain integrity of the structure. This should be carried as per the rectification methodology suggested by the experts of Bangalore University in their report.

Encl:- 2 sets of stability/ Conditional Assessment Report.

Yours Faithfully,

(Jyoti Shankar Behera)
कार्यपालक अभियंता-II,
कें.लो.नि.वि, बेंगलुरु -71

प्रतिलिपि:- The Asst. Engineer, BCSD 2/II, CPWD, Bangalore along with a copy of Assessment report.

कार्यपालक अभियंता-II,